


Pressure (bar)



Pressure loss curve.

— Soft spray

— Hard spray

bar	1	2	3	4	5	6
—	9.8	13.9	17.0	19.6	21.9	24.0
—	5.5	7.8	9.5	11.0	12.3	13.4

l/min