


Pressure (bar)



Pressure loss curve.

— Soft spray

— Hard spray

— Pulsating spray

bar	1	2	3	4	5	6
—	9.2	13.1	16.0	18.5	20.7	22.6
—	3.8	5.3	6.5	7.5	8.4	9.2
—	5.8	8.2	10.0	11.5	12.9	14.1

l/min